

Service 25 (Cleanjet Pump)



CleanJet does not deliver enough water to the fan wheel of the motor.
 Typical indication: The running time of the program will be exceeded.
 Check correct position of left rack and / or floor unit trolley!

